

Protection of human airways against harmful airborne solid particulates and/or liquids in aerosols (dust, smoke and mist) at a maximum exposure level of 10 times NDS (Polish Permissible Exposure Limit).

Use

Moderately toxic solid particulates, including asbestos, copper, barium, titanium, vanadium, chromium, and manganese; wood dust, carbon/coal dust with > 10% of free silica; intended for mining, chemical processing and metalworking (with the optional exhaust valve).

Specifications:

Half-mask dome:


- Polyester needled cloth
- Melt blown polypropylene non-woven cloth
- Outer coating needled cloth

Features:

- Exhaust valve
- Adjustable nose clip for a tight fit around the nose
- Polyethylene foam nose seal
- Head strap with fasteners for length adjustment
- Head straps

The improved and anatomically pre-formed nose section and the traditional nose clip provide a better seal.





Reference requirements

The half-mask complies with the latest requirements of:

Regulation (EU) 2016/425 of the European Parliament and of the Council of 9 March 2016 on personal protective equipment and repealing Council Directive 89/686/EEC.

Contraindications

Do not use in oxygen-deficient atmospheres (O2 < 17%); use inside confined spaces, including ducts, chambers, vaults, or tanks is prohibited. The half-mask does not protect against pollutants formed by harmful or lethal gases and vapours. Do not use when extinguishing fire. The half-mask is not a contained oxygen-supplying respirator. The seal is insufficient on a face with stubble or longer hair. The half-mask does not protect the respiratory system against aerosols of radioactive particles, viruses and enzymes.

Direct packaging: 50 pcs. in film bag Bulk container: 500 pcs./cardboard box Page 2 of